



NEICO AVIATION INC.

2244 Airport Way, Redmond, OR 97756 (541) 923-2244 Fax (541)923-2255

Service Bulletin 001-90

Subject: Lancair IV elevator control horn weldments

Date: August 20, 1992

Pages: 1

It has come to our attention that there was a batch of elevator control horn weldments that did not contain the elevator "control stop pads." These small pads are used when setting the elevator control travel limits.

Please inspect your components to verify that the two pads are included. See drawing below.

IF your control horn weldment does not have these pads, replacement will be necessary.

1. Send both component pieces (left and right) to Neico Aviation Inc., 2244 Airport Way, Redmond, OR 97756
- 2 Reference, on the OUTSIDE of the box, this service bulletin number, S13008-92.

We will promptly correct the situation and return the proper weldments to you. The corrected weldments are direct replacements and should not affect rib or bolt placement in the elevator.

We thank you in advance for your patience and cooperation.

Sincerely,
Neico Aviation Inc.

