



2244 Airport Way, Redmond, Oregon 97756 Phone 541 923-2233 Fax 541 923-2255

SERVICE BULLETIN

SB031-0497

Subject: Lancair IV nose gear door tab

Date: 1 May, 97

Ref:

Pages: 2

Status: Mandatory Change

Background:

We have had 2 reports from builders of their nose gear door tab being snagged by the wheel strap during retraction. This could possibly prevent nose gear extension.

Action:

Remove suspect tab on left and right nose gear doors. Check clearance by pushing the nose strut through the door while you are holding them slightly closed.

Note:

This is included as a revision in PC15 and C14/4 -10-97.

NOTE TO REV TECH:

USE PAGE 20-45 IN IV MANUAL FOR

2ND PAGE