



2244 Airport Way, Redmond, Oregon 97756 Phone 541 923-2233 Fax 541 923-2255

**SERVICE BULLETIN**

**SB044-0998**

Subject: Lancair Central Flap Actuator Cylinder Bellcrank (Lancair IV & IV -P)

Date: 21 Sept., 98

Ref: Part Number FL161-01

Pages 1

Status: Recommended Exchange

**Background:** We've had one case where this bellcrank's upper arm (that attaches to the flap actuating cylinder) has cracked. While static tests have repeatedly been satisfactory, we still feel that it is important to add a "finger strap" to this component which will prevent any possible breakage.

**Action:** This is an exchange program on a shared cost basis. Please remove and return your existing FL161-01 and we will immediately replace it with the modified version. The exchange cost is \$35.00. If your aircraft is flying and you need a very fast turnaround, please contact our office and we will expedite.

For fastest response, use the number 2003 with the first and last name of the owner. Example: (2003 John Doe)

