

PROPELLER MAINTENANCE RECORD

Position CTR

PITCH RANGE

Propeller Model HC-J3YF-1RF/F7391D-3 High/Feather 4.0

Propeller S/N JN937B Start Lock NA

Blade Design \_\_\_\_\_ Low 13.5

Blade S/N's Reverse NA

No. 1 M04908

No. 2 M04909

No. 3 M04910

No. 4 —

No. 5 —

No. 6 —



Aircraft Manufacturer Lancair International, LLC

Aircraft Model Legacy 22K


S/N 344

Registration N315WP

Spinner Assembly Part No. \_\_\_\_\_

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
Date: 5/14/2020 Hobbs: 0.0 ETT: 0.0	Registration: N315WP SN: L2K-344		Engine Model: IO550N19B SN: 1037637 [PROPELLER LOG]	 Lancair International, LLC. Uvalde, TX (KUA)
Installed Propeller, Hartzell Propeller INC Model HC-J3YF-1RF, Serial Number F7391D-3 this date. All associated paperwork has been attached to the aircraft records. ----- END -----				
 NAME _____			LICENSE _____	5/14/2020 DATE _____

Lancair International  
122 Howard Langford Drive  
Uvalde, TX 78801  
TEL (830) 423-3005



17-Aug-2021 N315WP Hartzell HC-J3YF-1RF/F7391D-3 S/N: JN937B Time: 96.1

Performed Condition Inspection IAW Lancair Legacy Condition Inspection Checklist. No defects noted.

I certify that this propeller has been inspected on **17-Aug-2021** in accordance with the scope and detail of appendix D to FAR Part 43, and was found to be in a condition for safe operation.

END

Joshua Johnson  
AP3624296
