



Cutting out trim tab  
Figure 7b:G.1



RIB  
AT INRD  
LOCATION



	320 FB- MK-II	7(B)-41	Chapter 7(B)	REV.	1 / 1-24-94
			HORIZONTAL STAB & ELEVATOR		

LANCAIR International, Inc., Distributed by New Airforce, Inc., Copyright © 1994, Bedford, OH 44108