



2244 Airport Way, Redmond, Oregon 97756 Phone 541 923-2233 Fax 541 923-2255

SERVICE BULLETIN

SB046-1298

Subject: New LIV Fast-Build Pitch Trim Tab

Date: 8th December, 1998

Ref: Construction manual, Chapter 31, Section G

Pages: N/A

Status: Mandatory Compliance

Lancair IV Trim Pitch Trim Tabs

In an ongoing effort to improve our products we have improved the design of the Lancair IV pitch trim tab. The design change effectively increases the rigidity of the trim tab. The change is mandatory to all the pre-molded trim tabs previously built.

The change will be done free of charge by Lancair. Please call our parts department for a return authorization number to ship your trim tab back.